| | DISCOVERY SITE EVALUATION CHECKLIST | | | | | | | |
|----|--|---|---|---------------|--|--|--|--|
| 1. | WIDS Site Code/Subsite Code: 600-400 | | | | | | | |
| 2. | Prepared and Reviewed By: | | | | | | | |
| | Christine Webb WIDS Analyst (print) | Signature | | - 15 pate | | | | |
| | Fred Ruck III | Makenta | 111-3/ | 45 | | | | |
| 3. | WIDS Regulatory SME (print) Comment: | Signature | | ate | | | | |
| | The waste site is mostly old lumber debris present. The debris covers an area of appro MSA Landuse Planning was inspecting Pit 14B lumber was noted on the southwest edge of t plaster like material and a coil of copper this location for a long time. | ximately 80 square feet . A debris pile consist he pit. It also include | . In February ing of mostly d some white, | 2015, old | | | | |
| 4. | Is the site a Solid Waste Management Unit? | | | ⊠ Yes | | | | |
| | Any discernible location at the Facility where solid wastes have been placed at any time, irrespective of whether the location was intended for the management of solid or dangerous waste, and includes any area at the Facility at which solid wastes have been routinely and systematically released (for example through spills), and includes dangerous waste treatment, storage, and disposal units. | | | | | | | |
| 5. | Does the site need to be addressed under a regulatory program? Check first item that applies. | | | | | | | |
| | General Description (see TPA-MP-14 for definitions) | Unit Category | Classification | Check Here | | | | |
| | Site specifically exempted from WIDS based on section 2.0 of TPA-MP-14 | Not Applicable | Not Accepted | | | | | |
| | Permitted RCRA TSD that will be addressed under a RCRA/CERCLA Coordination | RCRA/CERCLA Coordination TSD | Accepted | | | | | |
| | Permitted RCRA TSD | RCRA TSD | Accepted | | | | | |
| | Waste site that will be addressed as part of the closure of a RCRA TSD | RCRA TSD Related | Accepted | | | | | |
| | Waste disposal unit or unplanned release unit where radioactive or dangerous waste is present or possibly present | CERCLA Remedial/Removal Action | Accepted | | | | | |
| | Inert waste or limited purpose landfill (WAC 173-350-410 or WAC 173-350-400) | Inert Waste or Limited Purpose Landfill | Accepted | | | | | |
| | Solid waste landfill (WAC 173-350) | Solid Waste Landfill | Accepted | | | | | |

Page 1 of 2 A-6006-135 (REV 0)

| | DISCOVERY SITE EVAL | UATION CHECKLIST | | | |
|--------------|---|---------------------------------------|----------------|---------------|--|
| | Petroleum UST or contaminated soil from a petroleum UST leak (WAC 173-360) | Petroleum UST | Accepted | | |
| | Underground injection well that received noncontaminated effluent (e.g., storm water runoff, steam condensate, air conditioner condensate) (WAC 173-218) | Underground Injection Control Well | Accepted | | |
| | Other liquid disposal site with a State waste discharge permit (WAC 173-216) | State Waste Discharge | Accepted | | |
| | Septic system for which there is no expectation of radioactive or dangerous waste discharge (WAC 246-272 or WAC 246-272B) | Septic | Accepted | | |
| 6. | Assign the site to an operable unit or waste managem Applicable' if neither applies. | ent area. Write 'Not | N/A | | |
| 7. 8. | Ecology and EPA Approvals: Ecology Project Manager (print) Signature Date | | | | |
| 0. | Are any other activities needed or desired at the site? Only answer if no items in question 5 were checked. Check first item that applies. | | | | |
| | General Description | Unit Category | Classification | Check Here | |
| | A location where remediation is not needed, but debris removal or other miscellaneous restoration activities may be performed | Miscellaneous Restoration | Accepted | | |
| | A location where no remediation, miscellaneous restoration, permit closure or other physical (e.g., waste site remediation) or administrative (e.g., permit closure) activity is needed | Not Applicable | Not Accepted | | |
| 9. | DOE Approval: DOE Federal Project Director (print) | Marke | 3/1 | 7/15 | |